

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:			
OGM	Jim Smith Environmental Scientist III		
Company	Guy Davis Environmental Scientist		

Inspection Report

Permit Number:	C0150017		
Inspection Type:	COMPLETE		
Inspection Date:	Tuesday, December 16, 2003		
Start Date/Time:	12/16/2003 12:30:00 PM		
End Date/Time:	12/16/2003 2:20:00 PM		
Last Inspection:	Tuesday, November 25, 2003		

Inspector: Jim Smith, Environmental Scientist III

Weather: Cold, clear and sunny
InspectionID Report Number: 126

Accepted by: dhaddock 12/29/2003

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: DES BEE DOVE MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages		Mineral Ownership	Types of Operations
154.86 Tota	l Permitted	✓ Federal	✓ Underground
23.88 Tota	l Disturbed	✓ State	☐ Surface
F	Phase I	☐ County	Loadout
P	hase II	✓ Fee	Processing
Р	hase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

inspector	5 5	ıgnatu	re:
-----------	-----	--------	-----

Date Wednesday, December 17, 2003

Jim Smith, Environmental Scientist III Inspector ID Number: 43

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining



Permit Number: C0150017
Inspection Type: COMPLETE

Inspection Date: Tuesday, December 16, 2003

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading	✓			
13.	Revegetation	✓			
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.	a Roads: Construction, Maintenance, Surfacing	✓			
16.	b Roads: Drainage Controls	✓			
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		✓		
19.	AVS Check		✓		
20.	Air Quality Permit		✓		
21.	Bonding and Insurance	✓			
22.	Other		✓		

Permit Number: C0150017
Inspection Type: COMPLETE

Inspection Date: Tuesday, December 16, 2003 Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The bond is for \$1.837 million, with Traveler's Casualty and Surety Company of America. The new bond was signed on November 18, 2002 by Judi Johansen, executive vice-president of PacifiCorp.

The insurance policy is effective April 1, 2003 to April 1, 2004. The policy is with Associated Electric and Gas Insurance Services, Ltd., Hamilton, Bermuda. General liability is for \$2 million and excess liability is for \$20 million. The Division is named as the certificate holder, and the Division will be given 45 days advance notice of policy cancellation.

The current permit was effective August 30, 2000.

2. Signs and Markers

Still no bullet-holes in the new sign.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sedimentation pond has no remaining sediment storage capacity, based on the 3rd quarter survey. Results of the 4th quarter survey were not available.

4.d Hydrologic Balance: Water Monitoring

So far, during the 4th quarter there has been no discharge from the sedimentation pond, the only water monitoring location.